



An economical welding blanket or curtain material used to identify areas of a factory where welding or other activities are taking place that employees should take extra caution. This is a very standard material used for welding protection in Power Plants as well as Petrochemical Plants.

Applications: Curtains, Blankets, Flue Ducts, Gasketing and High Temperature Expansion Joints.

BASE CLOTH:	E-Glass
WEIGHT:	32 oz./yd ²
WEAVE:	Plain
THICKNESS:	0.060"
WIDTH:	40"
LENGTH:	50 yards
TEMPERATURE RESISTANCE:	Service Temperature 1000°F

Chemical Resistance: Resists most acids, alkalis and solvents except Hydrofluoric acid and hot phosphoric.